



Product Change Notification

TE Connectivity

Product Change Notification: E-20-001115

PCN Date: 29-JAN-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:

Relays SR2M/SR4/SR6 Force Guided

Description of Changes

The following part numbers will receive a new CCC certificate number until the 31st of October 2020, as the current CCC certificates will be canceled by 1st of November 2020. The relays will keep their CCC approval mark; Only the process and responsibility of CCC conformance declarations will change, given by the Chinese Government.

Reason for Changes:

Manufacturing / Process Requirements. Dear Customer, You are receiving this notice because TE Connectivity has record of you purchasing a part or multiple parts on the list below. These parts will receive new CCC certificate numbers and will keep their CCC approval marking. This change in the CCC approval procedure are based on the Rule change given by the Chinese Government, so TE will take over the responsibility of ensuring the conformance to CCC of these parts. Therefore, the creation of the "Self Declarations of Conformance" / SDOCs, will replace the currently used "compulsory certificates", issued by CCC, latest by October 31st 2020.

Estimated Dates:

Last Order Date (Obsolete Parts Only):	First Date To Ship (Changed Parts Only):
	01-MAR-2020
Last Ship Date (Obsolete Parts Only):	Last Date for Mixed Shipments: (Changed Parts Only):
	No Mixed Shipments

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-1	NO			"V23047-A1021-A501", "V23047A1021A501"			
1-1393258-5	NO			"V23047-A1024-A501", "V23047A1024A501"			
1-1393258-7	NO			"V23047-A1024-A511", "V23047A1024A511", "F97243-000", "AMPS-1-1393258-7"			
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1-1415012-1	NO			"V23047-A1110-A501", "V23047A1110A501"			
1393258-2	NO			"V23047-A1005-A501", "V23047A1005A501"			
1393258-4	NO			"V23047-A1012-A501", "V23047A1012A501"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
1415055-1	NO			"SR4D4012"			
3-1415006-1	NO			"V23047-A1048-A501", "V23047A1048A501"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415054-1	NO			"SR4M4048"			
3-1415055-1	NO			"SR4D4024"			
4-1415053-1	NO			"SR4M4024"			
5-1415053-1	NO			"SR4M4005"			
6-1415055-1	NO			"SR4D4048"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
6-1415537-5	NO			"SR6A6K24"			
7-1415054-1	NO			"SR4D4005"			
8-1415537-0	NO			"SR6B6K24"			
9-1415053-1	NO			"SR4M4018"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-1	NO			"V23047-A1021-A501", "V23047A1021A501"			
1-1393258-5	NO			"V23047-A1024-A501", "V23047A1024A501"			
1-1393258-7	NO			"V23047-A1024-A511", "V23047A1024A511", "F97243-000", "AMPS-1-1393258-7"			
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1-1415012-1	NO			"V23047-A1110-A501", "V23047A1110A501"			
1393258-2	NO			"V23047-A1005-A501", "V23047A1005A501"			
1393258-4	NO			"V23047-A1012-A501", "V23047A1012A501"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
1415055-1	NO			"SR4D4012"			
3-1415006-1	NO			"V23047-A1048-A501", "V23047A1048A501"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415054-1	NO			"SR4M4048"			
3-1415055-1	NO			"SR4D4024"			
4-1415053-1	NO			"SR4M4024"			
5-1415053-1	NO			"SR4M4005"			
6-1415055-1	NO			"SR4D4048"			
6-1415537-5	NO			"SR6A6K24"			
7-1415054-1	NO			"SR4D4005"			
8-1415537-0	NO			"SR6B6K24"			
9-1415053-1	NO			"SR4M4018"			

C

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393258-1	NO			"V23047-A1021-A501", "V23047A1021A501"			
1-1393258-5	NO			"V23047-A1024-A501", "V23047A1024A501"			
1-1393258-7	NO			"V23047-A1024-A511", "V23047A1024A511", "F97243-000", "AMPS-1-1393258-7"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
1-1393260-3	NO			"V23050-A1110-A542", "V23050A1110A542"			
1-1415012-1	NO			"V23047-A1110-A501", "V23047A1110A501"			
1393258-2	NO			"V23047-A1005-A501", "V23047A1005A501"			
1393258-4	NO			"V23047-A1012-A501", "V23047A1012A501"			
1393260-4	NO			"V23050-A1012-A542", "V23050A1012A542"			
1393260-7	NO			"V23050-A1024-A542", "V23050A1024A542"			
1415015-1	NO			"V23050-A1024-A533", "V23050A1024A533"			
1415055-1	NO			"SR4D4012"			
3-1415006-1	NO			"V23047-A1048-A501", "V23047A1048A501"			
3-1415018-1	NO			"V23050-A1021-A533", "V23050A1021A533"			
3-1415054-1	NO			"SR4M4048"			
3-1415055-1	NO			"SR4D4024"			
4-1415053-1	NO			"SR4M4024"			
5-1415053-1	NO			"SR4M4005"			
6-1415055-1	NO			"SR4D4048"			
6-1415537-5	NO			"SR6A6K24"			
7-1415054-1	NO			"SR4D4005"			
8-1415537-0	NO			"SR6B6K24"			
9-1415053-1	NO			"SR4M4018"			