

Product Change Notification - SYST-12XRF756

Date:

13 Feb 2020

Product Category:

32-bit Microcontrollers

Affected CPNs:**Notification subject:**

Data Sheet - SAM L21 Family Data sheet

Notification text:

SYST-12XRF756

Microchip has released a new Product Documents for the SAM L21 Family Data sheet of devices. If you are using one of these devices please read the document located at [SAM L21 Family Data sheet](#).

Notification Status: Final

Description of Change: This revision includes updates to formatting and the correction of typographical errors throughout the document.

1. Updated the SEQCTRL register
2. Updated the LUTCTRL register
3. Updated the following registers: CTRLA and STATUS
4. Updated the following registers for 8-bit, 16-bit and 32-bit:
 - a. EVCTRL
 - b. INTENCLR
 - c. INTENSET
 - d. NTFLAG
 - e. STATUS
 - f. DRVCTRL
 - g. SYNCBUSY
5. Updated the USERM register
6. Updated the CONFIGN register
7. Updated the VREF register
8. Updated the PWSAKDLY register
9. Updated the CPUDIV register
10. Updated the following registers: SYNCBUSY and GENCTRLn
11. Updated the STATUSB register
12. Updated the following registers: INTFLAGC and STATUSC

Impacts to Data Sheet: None

Reason for Change: To Improve Productivity

Change Implementation Status: Complete

Date Document Changes Effective: 13 Feb 2020

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

[SAM L21 Family Data sheet](#)



Please contact your local [Microchip sales office](#) with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our [PCN home page](#) select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the [PCN FAQ](#) section.

If you wish to change your PCN profile, including opt out, please go to the [PCN home page](#) select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and make the applicable selections.

Affected Catalog Part Numbers (CPN)

ATSAML21E15B-ANT
ATSAML21E15B-AUT
ATSAML21E15B-MNT
ATSAML21E15B-MUT
ATSAML21E16B-ANT
ATSAML21E16B-AUT
ATSAML21E16B-MNT
ATSAML21E16B-MUT
ATSAML21E17B-ANT
ATSAML21E17B-AUT
ATSAML21E17B-MNT
ATSAML21E17B-MUT
ATSAML21E18B-ANT
ATSAML21E18B-AUT
ATSAML21E18B-MNT
ATSAML21E18B-MUT
ATSAML21G16B-ANT
ATSAML21G16B-AUT
ATSAML21G16B-MNT
ATSAML21G16B-MUT
ATSAML21G17B-ANT
ATSAML21G17B-AUT
ATSAML21G17B-MNT
ATSAML21G17B-MUT
ATSAML21G18B-ANT
ATSAML21G18B-AUT
ATSAML21G18B-MNT
ATSAML21G18B-MUT
ATSAML21J16B-ANT
ATSAML21J16B-AUT
ATSAML21J16B-MNT
ATSAML21J16B-MUT
ATSAML21J17B-ANT
ATSAML21J17B-AUT
ATSAML21J17B-MNT
ATSAML21J17B-MUT
ATSAML21J17B-UUT
ATSAML21J18B-ANT
ATSAML21J18B-AUT
ATSAML21J18B-MNT
ATSAML21J18B-MUT
ATSAML21J18B-UUT