

PCN Number:	20131112000	PCN Date:	12/13/2013
Title:	TPS22980/TPS22981 datasheet		
Customer Contact:	PCN Manager	Phone:	+1(214) 480-6037
		Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Assembly Process
<input type="checkbox"/>	Design	<input checked="" type="checkbox"/>	Electrical Specification
<input type="checkbox"/>	Test Site	<input type="checkbox"/>	Packing/Shipping/Labeling
<input type="checkbox"/>	Wafer Bump Site	<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>	Wafer Fab Site	<input type="checkbox"/>	Wafer Fab Materials
		<input type="checkbox"/>	Part number change

PCN Details

Description of Change:

The product datasheet(s) is being update to add Rdisout description to datasheet and add an entry in the electrical characteristics table.

The following change history provides further details. These changes may be reviewed at the datasheet links provided



TPS22980

www.ti.com

SLVSB61C – DECEMBER 2011 – REVISED SEPTEMBER 2013

Changes from Revision B (April 2012) to Revision C

Page

- Removed ordering information table. 2
- Added R_{OUTDIS} parameter to the Electrical Characteristics table. 4
- Updated the DIGITAL CONTROL SIGNALS section. 8



TPS22981

www.ti.com

SLVSBM6A – DECEMBER 2012 – REVISED SEPTEMBER 2013

REVISION HISTORY

Changes from Original (December 2012) to Revision A

Page

- Removed ordering information table. 2
- Added R_{OUTDIS} parameter to the Electrical Characteristics table. 4
- Updated UVLO ENABLE section. 13

The datasheet number will be changing.

Device Family	Change From:	Change To:
TPS22980	SLVSB61B	SLVSB61C
TPS22981	SLVSBM6	SLVSBM6A

The updated datasheet(s) can be accessed by the following link(s):
<http://www.ti.com/product/tps22980>
<http://www.ti.com/product/tps22981>

Reason for Change:

To more accurately reflect device characteristics.

Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):

Electrical specification performance changes as indicated above.

Changes to product identification resulting from this PCN:

None

Product Affected:

TPS22980RGPR	TPS22981RGPR
--------------	--------------

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com